

EQUIPMENT KIT CHECKLIST

ARRI 1K FRESNEL KIT

OPERATION AND SAFETY:



ELECTROCUTION HAZARD

All instruments must be grounded (earthed). Never use ground-bypass adapters!



FLAMMABLE HEAT

Instruments operate at high temperatures. Do not operate upside-down!

Do not operate in the presence of flammable materials!

Maintain 3ft distance between instruments and surroundings!



BURN-RELATED INJURY

Instruments may remain extremely hot during and after operation.

May cause burns! Use protective gear! Before packing or handling, allow at least 10 minutes time for instruments to cool!

PACKING AND STORAGE:

IMPROPERLY OR MESSILY PACKED KITS WILL RESULT IN A FINE!

The Arri 1000 Plus is packed on its side, with its stirrup extended forward in front of the lens. Pack facing to the right, and base to the latch-side of the case, as labeled on the case foam.

Barndoor is packed separately, in the case-lid storage compartment, secured in place by its velcro strap. Make sure to lock the compartment's partition back into place. Do not pack the barndoor loose in the storage compartment!



AC Mains Cable should be neatly wrapped in alternating loops, and bound with their Velcro strap, fuzzy-side out. Lay the AC Cable on top of the instrument, as flat as possible. Do not pinch AC Mains Cable in case lid!

Do not throw away expired/broken lamps! Pack them in replacement lamps' boxes. The Equipment Checkout Lab will dispose of them properly! Borrowers will be billed for missing lamps!

NOTE: Lighting Stands are not included with this kit. Do not attempt to pack stands in this kit!

PACKING EXAMPLE:



In the event of accident or mishap with this equipment, contact the F&DM Checkout Lab Specialist IMMEDIATELY: Phone (831) 459-4062 – Email fdmcheckout@ucsc.edu

IN THE EVENT OF MEDICAL EMERGENCY, DIAL 911.